

Document ID# 1666651

2004 Cadillac CTS

---

## **Diagnostic Information on DTC P0894 and P1870 #02-07-30-001C - (May 31, 2005)**

Diagnostic Information on DTC P0894 and P1870

2000-2005 Passenger Cars and Light Duty Trucks

2003-2005 HUMMER H2

*2005 Saab 9-7X*

with 4L60-E or 4L65-E Automatic Transmission

This bulletin is being revised to add the 2005 Saab 9-7X to the models. Please discard Corporate Bulletin Number 02-07-30-001B (Section 07 -- Transmission/Transaxle).

Diagnostic trouble codes (DTC) P0894 and P1870, Transmission Component Slipping, may have different root causes. The following diagnostic tips are provided to assist in accurately repairing the condition.

- Corporate Bulletin Number 01-07-30-023B, dated March 2002, is intended for 1996-1999 vehicles with more than 32,000 km (20,000 mi). This bulletin addresses wear in the valve body TCC isolator/regulator bore, which can cause DTC P1870. This wear condition is not the cause of DTC P0894 or P1870 on any 2000 model year vehicle built after January 15, 2000, or any 2001 or newer vehicles as the valve body used on these vehicles has been revised to prevent the wear condition.
- Corporate Bulletin Number 99-07-30-005, dated March 1999, should be used to help with diagnosis of these DTCs. This bulletin will help to determine if the DTC is caused by the TCC system or by a slipping internal transmission component such as a clutch or band.
- Slip speeds greater than about 250 rpm at steady state driving are caused by a slipping clutch or band.

- Slip speeds ranging from approximately 100 to 250 rpm at steady state driving are usually caused by the TCC not applying but may also be caused by a slipping clutch or band.
- A plugged or restricted TCC apply fluid orifice (238, located in the pump) may cause DTC P0894 or P1870, especially in low mileage vehicles with less than 8,000 km (5,000 mi).
- A converter clutch valve (224, located in the pump), which does not have full travel of 13 mm (0.5 in) or is stuck in the off position may cause DTC P0894 or P1870. Inspect the valve for chips, debris, nicks or burrs. Also, inspect the springs (225 and 226) to make sure they are not limiting valve travel. A spring that is not fully wound may catch in the bore, limit valve travel and cause DTC P0894 or P1870.
- A cracked or leaking TCC solenoid (part of harness 66) may cause DTC P0894 or P1870. Use solenoid test kit J 44246 to test the operation of this solenoid.
- A cracked or leaking TCC PWM solenoid (396) may also cause DTC P0894 or P1870.

When attempting to diagnose a DTC P0894 or P1870, it is important to also refer to the appropriate Service Manual for further possible causes of this condition.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT  
VOLUNTARY  
TECHNICIAN  
CERTIFICATION

**© Copyright General Motors Corporation. All Rights Reserved.**

---

**Document ID# 1666651**  
**2004 Cadillac CTS**